



**Terästorni Oy**  
Muukonkankaantie 113  
FIN-53400 LAPPEERANTA  
FINLAND  
Tel: +358 5 627 0700

Fray Bentos, Uruguay, 05.07.2007

**FOR:**

**LBNiW**

**Laboratorium Badan Nieniszczacych  
i Wytrzymałościowych**

**Lucyna Berlinska**

90-330 Lodz, Al. Pilsudskiego 52/144  
tel./fax +48 42 6616503

**UDT CLDT Level II Certificate  
of Approval no. LB-180/14**

We brought LBNiW to Uruguay for the first time in 2006 to help us with the NDT work during the erection of multiple storage tanks and one massive pressure vessel on Botnia's Fray Bentos Pulp Mill.

When you bring in a new contractor there's often a lot of handholding, but we turned them loose and they did an outstanding job with very little interaction from us. LBNiW's quality workmanship and professionalism showed throughout all aspects on this project. Their inspectors were knowledgeable, proactive, and it was very easy to work with them.

LBNiW performed a comprehensive weld integrity testing of the 4,000m<sup>3</sup> PED class IV duplex pressure vessel which included 100% x-ray and extensive penetrant testing. Additionally, they conducted the inspection of welded joints of the 8 storage tanks by means of RT, UT, PT and MT. There were 2 large storage tanks with the capacity of 10,000m<sup>3</sup> each and a couple of smaller tanks.

Once again, thank you for the support you provided for our project. We will definitely look forward to working with you in the future.

  
OSSI VILHU  
MANAGING DIRECTOR

